Inspection Report

Name of work: Improvements to Roads and drains at Vijayalakshmi layout in Bagalagunte in ward No.14.

B.R. No.: 224/02-07-2016

Estimate Cost: 17.00 Lakhs

Bill Amount: 1571185-00

Name of the Agency: R.Shivaram

Date of Inspection: 06-12-2016

Observation and Conclusion:

The above said work "Improvements to Roads and drains at vijayalakshmi layout in Bagalagunte ward no 14" was shown to me by the Concerned Ward Engineer.

The above said work is inspected by me along with the Concerned Ward Engineer.

The work done is satisfactory

ASSISTANT EXECUTIVE ENGINEER
DASARALLI SUB DIVISION

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of work: Improvements to Roads and drains at Vijayalakshmi layout in Bagalagunte in ward No.14.

ASSISTANT EXECUTIVE ENGINEER
DASARALLI SUBDIVISION

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of work: Improvements to Roads and drains at Vijayalakshmi layout in Bagalagunte in ward No.14.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ASSISTANT EXECUTIVE ENGINEER
DASARALLI SUBDIVISION

SKETCH SHOWING IMPROVEMENTS TO ROADS & DRAINS AT VIJAYALAKSHMI LAYOUT, IN BAGALAGUNTE LAYOUT, WARD NO-14.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶಿಬ್ಬಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

ASSISTANT EXECUTIVE ENGINEER
DASARALLI SUB DIVISION

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT